

29<sup>th</sup> November, 2021**WORK COMPLETION CERTIFICATE**

This is to certify that **M/s. Dukhiram Maurya Engineering & Refractory Works (India) Pvt. Ltd.** had been engaged for the Furnace Side wall Hot Repair – Overcoating work during Canal Change RAK – 2021 Project in November, 2021.

They carried out Overcoating work for our 650 TPD Float Glass Furnace as per **Service Purchase Order No. GR047392, Dated: July 4, 2021** and Scope of Works mentioned below:

**Furnace Side Wall Overcoating: Left Hand and Right Hand, both sides**

**Overcoating on both sides – LHS & RHS from Port 0 to End of Refiner Section 2, up to the End of the Skimming hole:**

Port 0, Port 1 to Port 6, Refiner 1, Refiner 2 up to beginning of Glass Level Bowl Corners and under the Skimming Hole and Overcoating on the Furnace Waist Corners by removing First Generation Patch Blocks and Water Box Coolers wherever existing on the sidewalls and installing New Patch Blocks along with all Mechanical / Steel works related with Overcoating works.

The entire work was completed with good quality workmanship to our satisfaction and within stipulated time.

Dukhiram Team followed all the guidelines & instructions related with Environment, Health, Safety and COVID-19 of Guardian and have been found satisfactory with zero accident.

We appreciate the cooperation & support rendered by M/s. Dukhiram Maurya Engineering & Refractory Works (India) Pvt. Ltd. We found them reliable and committed Contractor.

**For Guardian Zoujaj International Float Glass Co. LLC**

Ayub Khan  
Plant Manager

