

**Registered Office :**

Gold Plus House, G-192, Prashant Vihar, Delhi-110085 (INDIA)

Ph : +91-11-47000500 • Fax : +91-11-47000555

E-mail : info@goldplusgroup.com • Website : www.goldplusgroup.com

**TO WHOM SOEVER IT MAY CONCERN**

This is to certify and confirm that M/s Dukhiram Maurya Engineering & Refractory Works (India ) Pvt. Ltd. were awarded the Contract for carrying out the Hot Repair of RHS Regenerator Chamber's common wall between 3<sup>rd</sup> and 4<sup>th</sup> chamber, Crown and Checker replacement of our 460 TPD Float Glass Furnace. The work was to be carried out with the Furnace in normal operating condition and Insertion of Water cooling Jacket in the Expansion joints of Port Nos 3 and 4.

The work was executed in a professional manner with all safety procedures being followed by their competent and dedicated team, resulting in No accident i.e. Zero accident. They also adhered to the specified time-schedule.

We thank M/s Dukhiram Maurya Engineering & Refractory Works (India) Pvt. Ltd. for their Customer Orientation and diligent Services and shall be happy to be associated with them for all such Hot Repair work at our Plant.

This letter is being issued as a Work completion Certificate, as desired by the party.

S.S.R. Murthy

 13.11.2014

Plant Head

**Gold Plus Glass Industry Limited**